

www.KOHOMM.org

Com. 798 - 9908, 794 - 4448

May 10, 2007

Ms. Carol Jones
DPW. Housing Division Chief

Subject: Reply from Seoul City regarding mercury tainted water issue

- 1. We, Korea Housing Management Company wish USFK prosperity eternally
- 2. We have been notified of higher-than-tolerated mercury levels in the water taken from Hannam Village for monthly water test.
- 3. To answer concerns of the residents we have contacted with the Seoul officials responsible for water and received the results that there was no sign of mercury after testing. For your reference, attached is the reply letter of Seoul City concerning this matter.

* Attachment : Copy of letter from Seoul City

Park, Sang Jin

19 15 21

Director of Hannam Village Management Office

ATTN: Director of Hannam Village Management Office

From: Seoul City Water Supply Operation

Subject: Reply to your concern

1. We wish your business prosperity.

- 2. This is in reference to document no. Hannam Village Management-336 dated on May 7, 2007.
- 3. With regard to your concern about mercury tainted water issue reported on Stars and Stripes, Seoul City tested water quickly taken from two installations mentioned in the paper and received safe results, well within acceptable limits.
- 4. Since samples taken on April 6 showed raised mercury level, Seoul City checked on test results conducted on April 4 at Tucksom Water treatment facility and the area which is being provided water by this facility. This test was conducted by authorized civil water test center and it didn't show any sign of problem. We confirm tap water provided by Seoul City is absolutely safe to drink.
- 5. Seoul City is equipped with internationally authorized facilities and manpower for water treatment range from Han River water source to faucet and provides water only after safely treated and validated.

Also, Seoul city has to alarm people immediately by law once problem detected. Safety of citizens is our top priority.

* Attachment: 2 sheets of test results.



상수도연구소



수신자 수신자참조

(경유)

제 목 수은 검출 보도 관련 수질검사 결과 보고(통보)

1. 수질과-1074(2007.05.08) "수질검사 등 지시"와 관련하여 수질검사를 실시한 결과를 아래과 같이 보고(공보)하오니 업무에 참고하시기 바랍니다.

--- 아래 ---

○ 의뢰일시 : 2007년 5월 7일(월)

○ 채 수 자 : 서부수도사업소(4점), 중부수도사업소(2점), 뚝도정수사업소(4점)

○ 채수지점 : 한남 외인 빌리지 외 10지점

○ 분석항목 : 수온(Hg)

※ 먹는물 수질기준 : <mark>0.001 mg/L이하.</mark> 정량한계 : 0.001 mg/L

○ 검사결과 : 10지점 모두 검출한계 <mark>0.0005 mg/L 이하로 불검출</mark>

宁 包		刀 酒	검사결과		
	4점	한남 빌리지 1동 1용 화장실	불검출		
서부		한남 빌리지 상가 2층 화장실 세면대	물검출		
수도사업소		한난 외인 발리지 관리동 2층 화장신	물검출		
		한남 중앙교회 수도꼭지	선 불검출		
중부	2점	인근 수요가(을지 6가 1-24)	불검金		
수도사업소	28	미육군 극동 공병단	불러준		
	4.24	침전수	불검출		
뜍도		통합 친전수	불검출		
청수사업소	4점	, 여과수	불검출		
		/ 정수	물검출		

※ 정량안계(먹는물관리법) : 0.001 mg/L, 검출안계(수돗물평가위원회) : 0.0005 mg/L

•

	시				- PM -	mg/L	4-1-11-1-1	CHOTHE	A 11 53 51	1 - 1 - 1	분원성대질	3 (7 + 5 11 5 11	1.7 1001
•	점 수 장 수원 및 선처리			구 의 최소자 - 8	4 5.0ppm Cl				X14	막 양취수장 -	<u>도</u>	il.	
5	수심 환경 소심 환경	程介	전수		H-III 크수	접수기	비고	원수	장수	지수	환병크수	전수기	HIL
今	음(10)/용종산소	9.0/11.1	10.0/11.6		11.0/11.6			10.0/12.1	10.0/11.9	10.5/11.7	10.0/11.4	-/5.7	
	재수시각	10:50	10:10	16:30	16:00	16:40		11:30	12:05	14:00	15:10	13:30	
거리,자제		2,1km		9Km	9km	9КМ	문행크	5km		8km	6Km	6Km	문행
		토막찬간관 1984	1984	아연도관한	1976	2005	('08.10월 청소,콘크	로부작장관	1992 임반적	스테인레스 2000	- 공관 2000	확인류능	('00.10
	<u> 건설인도</u>						리기지하	1992		1000000	#수지		천소,F FRP 8
	처리 곱쩡		위반석 정수처리		배수지 (80천문)	위배식 (08.4뛰어교체)	300m, 51.21 50m²)		정수처리		200천(교)	UF(06.4%) 웨메교웨)	m*)
		1	1	1		구 의					FF 12	on a manage particular	the plan make or
구분	10 号	환경기준	먹心作				수투만 정수기		粉令	전수 수		선생 경수	
			수취기준	원수	전수	지수	아메크	84.51	4000		马二二	14 1	Z7 ===
	워반세균		100이라	560		•		30	1500				I
発展	<u> </u>	1,0000 11		100			•		2/00	•	0	. 0	
11,1111	대진교	neneles	•	80	•	•	•		290				
7 71 41	<u>분원성대장관문</u>	2000 sh	0.06	50					250				
1 강 상 참대연합	남 산소	0.050[4]	0.05 1.5	0.10	0,07	0.07	1 0.07	0,09	0,09	0,07	0.07	0.06	7 0
기다 기다	III소	0.05016	0.05	B. 10	0,07	0.07	6	0,03	0,0.7	•		•	
~ MA 161	세례늄	0,000,00	0.01								6	•	
	수은		0.001				9		•	•		•	
	시안	•	0.01		•	9		•	•	•	•		
	62151	0.050 0	0,05						•		•		
	말묘니아성질소		0,5	0.30					0.18				
	취산성취소		10	1.9	1.8	1.8	1.8	1.9	1.8	1 1.B	T 1.8	1.8	1
	보끈		0.3		-	-			-				-
	카드뮴	0,0050 0	0.005				9	•			0	9	
감상	<u> </u>		0.005	•				0					
해연합 기료질	다이 <u>아지능</u> 파라티온		0.02			9	9						
4.51 th by	페니트로티온		0.04				6		-				
	카바다		0.07	-		9	9			6		0	-
	1.1.1-밀리를보였예만		0.1			9							
	테프라큐프교에門렛	0.040 0	0,01										
	그리큐로코에텐텐		0.03								•		
	데()로로메만	0,020 6	0.02	•									
	벤젠	0,010[0]	0.01										
	구구엑		0.7				•			•			
	<u>에</u> 데벤젠		0.3							0			-
- 애의(W)	크실덴		0,5	•			•	•					
기물점	1.1-디카로로에린덴	0.0040[4]	0.002	0			5					9	_
1	사업화탄소 1.2-6보요요-3-0요요표요만	0.004011	0,003			0				•	-		
- 作제。	잔묘역소		4.		0,68	0.37	0.30			0.62	0.45	0,28	
1	<u> 주트리합코메타</u>		0.1		0.016	0.019	0.019	0.002		0.016	0.020	0.023	î o
. 5	[0,080 2	0.08	•	0.0107	0.0129	0.0125	0.0019		0.0119	0.0139	0.0163	1 0.
	근로단하이트레이트		0.03		0.0031	0,0051	0,0039	•	•	0,0031	0,0033	0.0044	
	디프로모아세르니트[]		0.1	6			•						
	디를교도아세도니트린		0,09	•	0,0023	0.0032	0.0028			0.0026	0,0029	0,0035	
	고타(부교교아세고나그리	<u> </u>	0,004	•							A	•	1 -
	<u> 한로아세막에서도</u>		0.1	•	0.0137	0.0170	0.0154	a		0.0109	0.0177 60	0.0211	0.
시미적	경도		300	5,7	71	73	72	71	5.4	1,6	1,3	1.9	-
ខាល់លា ក	<u>과망간산칼읍소비당</u> 될세		10 	0				9	0			•	
	· 맛		무미	0		•		•	0	9			
	8		1	•	0		6		•			0.014	0
	색 <i>도</i> .		5	7		0	•		7			9	
	세제		0,5							. •	. •		
	수소이목농모	6,5-B,5	5,8~8.5	1 8.3	7.1	7.5	7.5	7.6	8.5	7.5	7.4	7.4	Ī
	아연		1	0.006			0.003	0.018	0.010	0.002	0.005	0.005	0
	면소이온		250	12	20	20	20	20		18	18	1 21	1
	<u> 증발작유</u> 안		500	125	194	126	127	124	121	123	120	120	Ī
	<u></u>		0.3	0,16					0.15	0		0	-
	다간		0.3	0,015	4 000	♦ 0.06	♦ 0.07	↑ 0.08	0.017 4.20	0.08	0.08	0.08	1
	막또(NTU)		0,5*/1	4.40	0.08	1:	1		-			13	tk '
	황산이옵		2,00	15	15	15	15	15	15	T 15	14	11	П

왕산이다 200 15 15 15 15 15 15 15 14 14 14 14 [만간 미술 0.2 0.26 0.04 0.04 0.04 0.03 0.24 0.05 0.05 0.03 0.02 보전반한계 미만인 경우, 또는 왕전기조 및 유용수가쇼에서 건출되지 않아야 함 경구 ● (요결홍, ●.NOT Definated)과 결출인 경우 ○ (DT, Definated),과 결출인 전우 ○ (DT, Definated),과 결출인 전후 ○ (DT, Definated),과 전후 ○ (DT, 환경기종(), 음유수 수집기조()에 대비 비효편가라였으며, 원수수집은 환경기준, 및 역본요수집기준에 대비 평가하였다.

수신자 수질과장, 중부수도사업소장, 서부수도사업소장

정관조 수취뿐석과장 박현 수진연구부장 ★담당자 한선의 소장

05/08 점보의

인조자

시핵 수진분석과-1323 (2007.05.08.) 접수 수질과-1083 (2007.05.08.)

우 143-820 서울특별시 광진구 구의2동 130-1 / 홈페이지www.water.seoul.go.kr

전화 02)2049-1071 /전송 02)2049-1013 / 이메일Jgjwater@seou'.go.kr / 공개